



## **CERTIFICATE OF CONSTANCY OF PERFORMANCE**

Issued by DBI Certification, notified body No. 2531.

In compliance with Regulation 305/2011/EU of the European Parliament and of the Council of 9 March 2011 (the Construction Products Regulation or CPR), this certificate applies to the construction product

#### **Orbis Class BS Conventional Heat Detectors**

The product fulfils the essential characteristic:

See Annex 1

Intended use: Applications related to automatic fire alarm systems

Placed on the market under the name or trade mark of:

Apollo Fire Detectors Ltd. 36 Brookside Road

Havant, Hampshire, GB-P09 1JR

United Kingdom

and produced in the manufacturing plant:

Apollo Fire Detectors Ltd. 36 Brookside Road Havant, Hampshire, GB-P09 1JR United Kingdom

This attests that all provisions concerning the performance described in Annex ZA of the standard(s)

EN 54-5:2017/A1:2018 : Fire detection and fire alarm systems - Part 5: Heat detectors - point heat detectors

under system 1 for the performance set out in this certificate are applied and that the factory production control conducted by the manufacturer is assessed to ensure the

## CONSTANCY OF PERFORMANCE OF THE CONSTRUCTION PRODUCT.

This certificate was first issued on 2019-10-09 and will remain valid as long as neither the harmonised standard, the construction product, the AVCP methods nor the manufacturing conditions in the plant are modified significantly, unless suspended or withdrawn by the notified product certification body.

The attached annexes form part of this certificate.

Date of issue: 2022-06-30

(This certificate supersedes the previous version of this certificate issued 2019-10-09)

Merete Poulsen Responsible for evaluation

Responsible for certification decision

The certificate shall be reproduced in extenso
– extracts only with written permission from DBI Certification A/S.





Annex 1

### **EXTENT**

### **Model Reference:**

**Orbis Class BS Conventional Heat Detectors** 

#### Variants:

ORB-HT-11004-APO Orbis Class BS Heat Detector with SensAlert and FasTest

ORB-HT-11016-APO Orbis Class BS Heat Detector with Flasing LED, SensAlert and FasTest

OEX-HT-11040-APO Orbis Class BS Heat Detector with Flashing LED and SensAlert

OEX-HT-11092-APO Orbis Class BS Heat Detector with SensAlert

#### Bases:

OB: ORB-MB-00001-APO TimeSaver base

OL: ORB-MB-00002-APO TimeSaver base LX (without continuity checking link)

OD: ORB-DB-00003-APO TimeSaver diode base

OR:ORB-RB-10004-APO TimeSaver relay base

XL: ORB-MB-00012-APO & OEX-MB-00016-APO LX bases

EB: ORB-MB-00019-APO TimeSaver deep base

#### Ancillary

ORB-BA-10008-APO Adaptor Base (to be used in conjunction with the following bases only: 45681-200 & 45681-201)

### **Description:**

Class BS Adressable Heat Detector intend for use in fire detection and fire alarm systems intalled in and around buldings. With additional test for Suffix S detectors.

#### **Operating Voltage:**

8.5 to 33 V DC

### **Heat Response Catergory:**

\*For detector categories with the suffix S or R, additional requirements are needed see 4.4.1 or 4.4.2

### Table 1

Detector Category (Heat Class):	Typical Application Temperature	Maximum Application Temperature °C	Minimum Static Response Temperature °C	Maximum Static Response Temperature °C
BS	40	65	69	85

### **Table 2- Response time limits**

Rate of rise of				
air temperature K min-1	Lowe	er limit	Uper	limit
	Min	S	Min	S
1	29	0	46	0
3	7	13	16	0
5	4	9	10	0
10	2	0	5	30
20	1	30	3	13
30		40	2	25



<sup>-</sup> extracts only with written permission from DBI Certification A/S.





Essential characteristics	Clauses in EN 54-5:2017/ A1:2018	Regulatory classes	Performance
Operational reliability:			
Position of heat sensitive element	4.2.1		The heat sensitive element(s) or at least part of it, except elements with auxiliary functions (e.g.characteristic correctors), are a distance ≥15mm from the mounting surface of the point heat detector.
Individual alarm indication	4.2.2		Category BS The heat detector is provided with an integral red visual indicator and can remain identified until the alarm is reset. The visual indicator is visible from a distance of 6 m directly below the point heat detector, in an ambient light intensity up to 500 lx.
Connection of ancillary devices	4.2.3		Open or short circuit failures of connection to ancillary device do not prevent the correct operation of the detector
Monitoring of detachable point heat detectors	4.2.4		A fault condition is signaled when the detector is remove from the mounting base.
Manufacturer's adjustments	4.2.5		It is not possible to change the maufacture's settings expept by special means (e.g. a special code or tool, or by breaking or remove a seal).
Onsite adjustments of response behavior	4.2.6		N/A
Software controlled detectors (when provided)	4.2.7	BS	The software documentation and the software design complies supplied by the manufacturer with the requirements of this standard.
Nominal activation conditions/Sensitivity:		1	
Directional dependence	4.3.1		The response time of the point dectetor do not unduly depend on the direction of airflow around the point heat detector.
Static response temperature	4.3.2		The response temperatures of the point heat detectors libetween the minimum and maximum static response temperatures, according to the category of the point heat detector in Table 1 above.
Response times from typical application temperature	4.3.3		The response times of the point heat detector lie between the lower and upper response time limits for the appropriate point heat detector category in Table 2 above.
Response times from 25 °C	4.3.4		The response time at 3 K min <sup>-1</sup> exceeds 7 min 13 s and th response time at 20 K min <sup>-1</sup> exceeds 1 min 0 s.
Response times from high ambient temperature	4.3.5		No alarm or fault signal was given at high ambient temperatures appropriate to the anticipated service temepratures.



<sup>–</sup> extracts only with written permission from DBI Certification A/S.





		BS 3 K min <sup>-1</sup> , Lower limit, 1 min 20 s and upper limit 16 m. 20 K min <sup>-1</sup> , Lower limit, 12 s and upper limit 3 m 13 s.
Reproducibility	4.3.6	The response times of the point heat detectors lie between the lower ad upper response time limits specified in Table 2 above.
Response delay (response time):		
Additional test for suffix S point heat detectors	4.4.1	Suffix S point heat detector did not exceed the lower limits of response time during the transer period or during the 10 min exposure below.
		Point heat detector category  Conditioning Airflow Temperature °C Temperature °C
		BS 20 ±2 65 ±2
		Rate of rise of air temperature K min <sup>-1</sup> Lower Limit response time
		Min S 3 9 40
		5 5 48
		10 2 54
		20     1     27       30     58
Additional test for suffix R point heat detectors	4.4.2	N/A
Tolerance to supply voltage:		
Variation in supply 4.5 The point heat detect variation in the supply		The point heat detector does not unduly depent on variation in the supply parameters and lie between the lower and upper response time limits specified in Table 2 above.
Durability of nominal activation conditions/Sensitivity:		
temperature resistance	4.6.1.1	No clares of facilities during the last of
Cold (operational)	4.6.1.1	No alarm or fault signal was given during the transition to the conditioning temperature or during the period at the condition temperature
		Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.
		BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6
Dry heat (endurance)	4.6.1.2	No fault signal was given on reconnection attributable to the endurance conditioning



The certificate shall be reproduced in extenso  $% \left( \mathbf{r}\right) =\mathbf{r}^{\prime }$ 

– extracts only with written permission from DBI Certification A/S.





		Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6
Humidity resistance	4.00.1	Mandama of C. H. C. L. C
Damp heat, cyclic (operational)	4.6.2.1	No alarm or fault signal was given during the conditioning.
(operational)		conditioning.
		Lower temperature: (25±3) °C
		Upper temperature: (40±2) °C
		Relative humidity:
		At lower temperature :≥ 95 % At upper temperature : (93 ±3) %
		At upper temperature . (33 ±3) 70
		Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s
		and did not exceed 2 min 40 s compared with the time
		obtained in 4.3.6.
		BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed
		30 s compared with the time obtained in 4.3.6
		30 3 compared with the time obtained in 11310
Damp heat, steady-state	4.6.2.2	No fault signal was given on reconnection attributable to
(endurance)		the endurance conditioning.
		0 199
		Conditioning Temperature: 40 ±2 °C
		Relative Humidity: 93 ±3 %
		Duration: 21 days
		Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s
		and did not exceed 2 min 40 s compared with the time
		obtained in 4.3.6.
		BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed
		30 s compared with the time obtained in 4.3.6
Corrosion resistance		N. C. H
Sulphur dioxide (SO <sub>2</sub> ) corrosion (endurance)	4.6.3	No fault signal was given on reconnection attributable to the endurance conditioning.
corrosion (endurance)		the endurance conditioning.
		Conditioning
		Temperature : 25 ±2 °C
		Relative Humidity: 93 ±3 %
		SO2 concentration: 25 ±5 ppm (by volume)
		Duration: 21 days
		Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s
		and did not exceed 2 min 40 s compared with the time
		obtained in 4.3.6.
		DC. 20 K mind was not been then 4 min and did .
		BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6
		50 3 compared with the time obtained in 4.3.0
		*



<sup>–</sup> extracts only with written permission from DBI Certification A/S.





No alarm or fault signal was given during the conditioning period or an additional 2 min.	Vibration resistance		
conditioning period or an additional 2 min.  For specimen with a mass ≤ 4,75 kg:  Shock pulse type: Half sine Pulse duration: 6 ms Peak acceleration: 10X (100-20M) ms-2 (M is specimen mass in Kg) Number of directions: 6 Pulses per direction: 3  Response time at 3 K min¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,11 Hammer velocity: 1,5 ±0,13 ms¹ Number of impacts: 1  Response time at 3 K min¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms x²(=0,5 g <sub>a</sub> ) Number of axes: 3 Sweep rate: 1 octave min² Number of sweep cycles: 1 per axis  Response time at 3 K min¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz  Vibration, sinusoidal (endurance)  Conditioning: Frequency range: 10 to 150 Hz		4.6.4.1	No alarm or fault signal was given during the
For specimen with a mass \$ 4,75 kg :  Shock pulse type: Half sine Pulse duration: 6 ms Peak acceleration: 10X (100-20M) ms-2 (M is specimen mass in kg) Number of directions: 6 Pulses per direction: 3  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>0</sub> ). Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz	(-1	· · <u>-</u>	
Shock pulse type: Half sine Pulse duration: 6 ms Peak acceleration: 10X (100-20M) ms-2 (M is specimen mass in kg) Mumber of directions: 6 Pulses per direction: 3 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 3 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No alarm or fault signal was given during the conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (-0,5 g <sub>m</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning. Conditioning: Frequency range: 10 to 150 Hz			
Pulse duration: 6 ms Peak acceleration: 10X (100-20M) ms-2 (M is specimen mass in Kg) Number of directions: 6 Pulses per direction: 3 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>o</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of save 1 per axis Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (operational)  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning. Conditioning: Frequency range: 10 to 150 Hz			For specimen with a mass ≤ 4,75 kg:
Pulse duration: 6 ms Peak acceleration: 10X (100-20M) ms-2 (M is specimen mass in Kg) Number of directions: 6 Pulses per direction: 3 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>o</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of save 1 per axis Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (operational)  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning. Conditioning: Frequency range: 10 to 150 Hz			Shock nulse type: Half sine
Peak acceleration: 10X (100-20M) ms-2 (M is specimen mass in Kg) Number of directions: 6 Pulses per direction: 3 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-2</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-2</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>n</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (and the exceed 2 min 40 s compared with the time obtained in 4.3.6.  No fault signal was given during the conditioning Conditioning in 4.6.4.4 (and not exceed 2 min 40 s compared with the time obtained in 4.3.6.  No fault signal was given on reconnection attributable to the endurance conditioning. Conditioning: Frequency range: 10 to 150 Hz			
mass in kg) Number of directions: 6 Pulses per direction: 3  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (±0,5 g <sub>0</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given our per conditioning conditioning conditioning and side not exceed 2 min 40 s compared with the time obtained in 4.3.6.  No fault signal was given our per condition attributable to the endurance on reconnection attributable to the endurance conditioning. Conditioning: Frequency range: 10 to 150 Hz			
Number of directions: 6 Pulses per direction: 3 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1 Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>n</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  Response time at 3 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)			
Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1.9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Wibration, sinusoidal (operational)  4.6.4.3  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>n</sub> )  Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning: Frequency range: 10 to 150 Hz			
and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No alarm or fault signal was given during the conditioning; Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms¹ Number of impacts: 1  Response time at 3 K min² was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  4.6.4.3  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  4.6.4.4  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  Acceleration amplitude: 5 ms²(≈0,5 g₀) Number of axes: 3 Sweep rate: 1 octave min² Number of sweep cycles: 1 per axis  Response time at 3 K min² was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning: Frequency range: 10 to 150 Hz			Pulses per direction: 3
and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No alarm or fault signal was given during the conditioning; Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms¹ Number of impacts: 1  Response time at 3 K min² was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  4.6.4.3  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  4.6.4.4  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  Acceleration amplitude: 5 ms²(≈0,5 g₀) Number of axes: 3 Sweep rate: 1 octave min² Number of sweep cycles: 1 per axis  Response time at 3 K min² was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning: Frequency range: 10 to 150 Hz			
obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Wibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  A6.4.3  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  A6.4.4  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  Vibration, sinusoidal (operational)  A6.4.4  Conditioning: Frequency range: 10 to 150 Hz			1 '
BS: 20 K min¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6			
Impact (operational)  4.6.4.2  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms¹ Number of impacts: 1  Response time at 3 K min¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms²(≈0,5 g₀) Number of axes: 3  Sweep rate: 1 octave min² Number of sweep cycles: 1 per axis  Response time at 3 K min² was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			obtained in 4.3.6.
Impact (operational)  4.6.4.2  No alarm or fault signal was given during the conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms¹ Number of impacts: 1  Response time at 3 K min¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms²(≈0,5 g₀) Number of axes: 3  Sweep rate: 1 octave min² Number of sweep cycles: 1 per axis  Response time at 3 K min² was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6.  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			DC: 20 K asias1as not less then 1 usin and did not sussed
Impact (operational)  4.6.4.2  No alarm or fault signal was given during the conditioning: Impact energy: 1,9±0,1 J Hammer velocity: 1,5±0,13 ms¹ Number of impacts: 1  Response time at 3 K min¹was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms²(=0,5 g <sub>n</sub> ) Number of axes: 3 Sweep rate: 1 octave min¹ Number of sweep cycles: 1 per axis  Response time at 3 K min¹was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Wibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given during the conditioning conditioning: Frequency range: 10 to 150 Hz  Conditioning: Frequency range: 10 to 150 Hz  Conditioning: Frequency range: 10 to 150 Hz			
conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>n</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			30 3 compared with the time obtained in 4.3.0
conditioning period or an additional 2 min.  Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>n</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz	Impact (operational)	4.6.4.2	No alarm or fault signal was given during the
Conditioning: Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (=0,5 g <sub>n</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning: Frequency range: 10 to 150 Hz			
Impact energy: 1,9 ±0,1 J Hammer velocity: 1,5 ±0,13 ms¹ Number of impacts: 1  Response time at 3 K min¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms²(≈0,5 gn) Number of axes: 3 Sweep rate: 1 octave min² Number of sweep cycles: 1 per axis  Response time at 3 K min² was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  B5: 20 K min² was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (conditioning: Frequency range: 10 to 150 Hz			
Hammer velocity: 1,5 ±0,13 ms <sup>-1</sup> Number of impacts: 1  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (≈0,5 g <sub>n</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  Conditioning: Frequency range: 10 to 150 Hz			
Number of impacts: 1  Response time at 3 K min¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms²(≈0,5 gn) Number of axes: 3 Sweep rate: 1 octave min¹ Number of sweep cycles: 1 per axis  Response time at 3 K min¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  Wibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (≈0,5 g <sub>n</sub> ) Number of axes: 3  Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms⁻²(≈0,5 gn) Number of axes : 3 Sweep rate: 1 octave min⁻¹ Number of sweep cycles: 1 per axis  Response time at 3 K min⁻¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  Conditioning: Frequency range: 10 to 150 Hz			Number of impacts: 1
and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms⁻²(≈0,5 gn) Number of axes : 3 Sweep rate: 1 octave min⁻¹ Number of sweep cycles: 1 per axis  Response time at 3 K min⁻¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  Conditioning: Frequency range: 10 to 150 Hz			Decrease time at 2 K minuture not less than 7 min 12 a
obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms <sup>-2</sup> (≈0,5 g <sub>n</sub> ) Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6    Vibration, sinusoidal (operational)   Vibration, sinusoidal (operational)   Vibration, sinusoidal (operational)   Vibration, sinusoidal (operational)   Vibration, sinusoidal (endurance)   Vibration, sinusoidal (endurance)   Vibration, sinusoidal (endurance)   Vibration, sinusoidal (operational signal was given on reconnection attributable to the endurance conditioning.   Vibration of the signal was given on reconnection attributable to the endurance conditioning.   Vibration of the signal was given on reconnection attributable to the endurance conditioning.   Vibration of the signal was given on the signal was			·
Vibration, sinusoidal (operational)  4.6.4.3  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms⁻²(≈0,5 gn) Number of axes : 3 Sweep rate: 1 octave min⁻¹ Number of sweep cycles: 1 per axis  Response time at 3 K min⁻¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  Vibration, sinusoidal (endurance)  Conditioning: Frequency range: 10 to 150 Hz			obtained in 4.5.0.
Vibration, sinusoidal (operational)  4.6.4.3  No fault signal was given during the conditioning Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms⁻²(≈0,5 gn) Number of axes : 3 Sweep rate: 1 octave min⁻¹ Number of sweep cycles: 1 per axis  Response time at 3 K min⁻¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  Vibration, sinusoidal (endurance)  Conditioning: Frequency range: 10 to 150 Hz			BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed
Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms⁻²(≈0,5 gn) Number of axes: 3 Sweep rate: 1 octave min⁻¹ Number of sweep cycles: 1 per axis  Response time at 3 K min⁻¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  4.6.4.4  Conditioning: Frequency range: 10 to 150 Hz			
Conditioning: Frequency range: 10 to 150 Hz Acceleration amplitude: 5 ms⁻²(≈0,5 gn) Number of axes: 3 Sweep rate: 1 octave min⁻¹ Number of sweep cycles: 1 per axis  Response time at 3 K min⁻¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  4.6.4.4  Conditioning: Frequency range: 10 to 150 Hz			
Frequency range: 10 to 150 Hz  Acceleration amplitude: 5 ms⁻²(≈0,5 gn)  Number of axes: 3  Sweep rate: 1 octave min⁻¹  Number of sweep cycles: 1 per axis  Response time at 3 K min⁻¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz		4.6.4.3	
Acceleration amplitude: 5 ms⁻²(≈0,5 gn) Number of axes: 3 Sweep rate: 1 octave min⁻¹ Number of sweep cycles: 1 per axis  Response time at 3 K min⁻¹ was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min⁻¹ was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  Vibration, sinusoidal (endurance)  4.6.4.4  Conditioning: Frequency range: 10 to 150 Hz	(operational)		
Number of axes: 3 Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
Sweep rate: 1 octave min <sup>-1</sup> Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
Number of sweep cycles: 1 per axis  Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			Nulliber of sweep cycles. I per axis
and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s
obtained in 4.3.6.  BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6  Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			·
Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			· ·
Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
Vibration, sinusoidal (endurance)  4.6.4.4  No fault signal was given on reconnection attributable to the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			
(endurance) the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz			30 s compared with the time obtained in 4.3.6
(endurance) the endurance conditioning.  Conditioning: Frequency range: 10 to 150 Hz	Milanakian airwa-talal	4.6.4.4	No fault signal uses signs as a second section at the second seco
Conditioning: Frequency range: 10 to 150 Hz		4.6.4.4	
Frequency range: 10 to 150 Hz	(endurance)		the endurance conditioning.
Frequency range: 10 to 150 Hz			Conditioning:
Acceleration amplitudes to more than Kill			Acceleration amplitude: 10 ms <sup>-2</sup> (≈1,0 g <sub>n</sub> )
Number of axes : 3			
Sweep rate: 1 octave min <sup>-1</sup>			



<sup>–</sup> extracts only with written permission from DBI Certification A/S.





		Number of sweep cycles: 20 per axis
		Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.
		BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6
Electrical stability EMC immunity (operational)	4.6.5	Compliance in EN 50130-4:2011 and No fault signal was given during the conditioning.
		Response time at 3 K min <sup>-1</sup> was not less than 7 min 13 s and did not exceed 2 min 40 s compared with the time obtained in 4.3.6.
		BS: 20 K min <sup>-1</sup> was not less than 1 min and did not exceed 30 s compared with the time obtained in 4.3.6

### Annex 2

#### **TEST DOCUMENTATION**

TEST DOCUMENTATION		
Accredited Laboratory	Report no.	Date
BRE	TE 210363 SW	2003-05-01
BRE	211499	2004-01-05
BRE	TE 211499 SW/B	2004-03-29
BRE	TE 211499 SW/A	2004-12-22
BRE	TE P105641-1001 Issue: 1	2018-10-31

### **TECHNICAL BASIS**

File Number	Title
400-HT-00001	Build Standard
400-HT-00002	Build Standard
ORB-MB-00001	Build Standard no. 300-MA-00003
ORB-MB-00002	Build Standard no. 300-MA-00006
ORB-DB-00003	Build Standard
ORB-RB-10004	Build Standard 400-RB-00007
ORB-MB-00012	Build Standard
ORB-MB-00019	Build Standard 300-MA-00012



<sup>–</sup> extracts only with written permission from DBI Certification A/S.